

TEST REPORT XC3166

Testing of Clear Automotive Coating



CMSE Report XC3166

This Report is subject to binding obligations under which it was prepared. In particular, the Report must not be used:

- as a means of endorsement; or
- in a company prospectus or notification to a Stock Exchange document for capital raising, without the prior written consent of CSIRO.

The Report may be published verbatim and in full, provided that a statement is included on the publication that it is a copy of the Report issued by CSIRO.

Excerpts of the Report may not be published without the prior written consent of CSIRO

Client:	Zen Automotive Suppliers Pty Ltd
ABN:	
Contact:	Joel Blake Managing Director
Address:	Unit 11/12 Stanton Road Seven Hills NSW, 2147
Tel:	+61 2 1300 599 616
Fax:	+61 2 8079 6603
Email:	joel@zas.com.au
Report Author:	Gerry Eccleston M App Sc.
Tel:	03 9252 6362
Fax:	03 9252 6011
Email:	Gerald.Eccleston@csiro.au

Date of Report: 31 October 2012



1.0 INTRODUCTION

At the request of Joel Blake, Zen Automotive Supplier, clear coated card were tested for Scratch and Chemical Resistance.

The sample supplied consisted of 195x290 mm cards coated with Opticoat Batch D6071812A applied on 18/07/2012 by Zen Automotive Suppliers.

2.0 TEST METHODS

2.1 Scratch Resistance

The scratch resistance was determined in accordance with AS 1580 Method 403.1 'Scratch resistance'. A tungsten carbide needle is slid over the surface. The load required for the needle to penetrate through to the substrate is used to indicate the scratch resistance. A maximum of 2000 gm load is used.

2.2 Test Conditions and Timing

Ambient conditions at the time of the test/s were $23 \pm 3^{\circ}$ C and $45 \pm 15^{\circ}$ RH thereby complying with AS/NZS 1580.101.5

The testing was undertaken on the 30 October 2012 and the results pertain to the samples as received.

2.3 Chemical Resistance

The chemical resistance of the coating was determined in accordance with ASTM D1308-02 'Effect of Household Chemicals on Clear and Pigmented Organic Finishes'

Concentrated Hydrochloric acid, Phosphoric acid, and Ethanol were applied to the surface of the coating, covered and allowed to be in contact with the surface for one hour. The surface was then washed with distilled water, allowed to dry and then inspected.



3.0 RESULTS

The results are detailed below.

Client Sample No	XC3166
Sample Details	Opticoat Batch D6071812A applied on 18/07/2012
Scratch Resistance AS 1580 Method 403.1	1100 g
Chemical Resistance ASTM D1308-02	Conc. Hydrochloric Acid;: No effect Conc. Phosphoric Acid: No effect Ethanol: No effect

GEachton

Senior Materials Scientist 31 October 2012